



To

The Principal
P.M.Shri GSS School
Dhoolgarh Guldhera
District Kurukshetra

No. 923

Dated: 02/04/2024

Subject: Regarding issuance of Building Safety Certificate

Reference: Your office letter No. 3109 dated 27.2.2023

In this connection, it is submitted that the building of P.M.Shri GSS School, Dhoolgarh Guldhera District Kurukshetra has been inspected by the Sub Division No.1, PWD B&R, Pehowa along with concerned Junior Engineer and building found to be safe as per visual inspection of the structure of the building. The school Building Safety Certificate is hereby given upto the period 2024-25 with the following conditions:-

1. Building of this school should be repaired every year.
2. Water should not be allowed to stagnate around and on the roof of the Building.
3. If Building is found cracked from anywhere, the same should be got vacated immediately and same should be got repaired immediately.
4. School will be responsible for safety of building from every angle and Fire-Fighting equipment should be in functional condition.
5. If the building of the school is to be extended, the same should be first approved from Structural Engineer.
6. Adequate Fire safety may be adopted in the school campus.
7. School authority shall also ensure safety precautions from false ceiling and vitrified tiles used in dado.
8. NOC may be considered as cancelled by this office if the college violates any of the above points.

DA/Nil
Endst No.

Dated

Copy forwarded to the SDE, PSD-1, PWD B&R, Pehowa w.r.t his letter No. 237 dated 28.3.2024.

DA/Nil

Executive Engineer,
Provincial Division No.1,
PWD B&R, Kurukshetra

Executive Engineer,
Provincial Division No.1,
PWD B&R, Kurukshetra